


FIG. I



2/5

FIG. 2




FIG. 3

## 4/5




FIG. 4



## 5/5

TIME (min)	SET TEMPERATURE (°C)	CHANGE RATE OF SET TEMPERATURE (°C/min)
	(Set Point)	(Ramp Rate)
t 0~t 1	3 0 0	0
t 1~t 2	300~310	1 0
t 2~t 3	310~350	2 0
t 3~t 4	350~400	5 0
t 4~t5	400~500	1 0 0
t5~t6	500	0
t 6~t 7	500~400	-100
t7~t8	400~350	<b>-</b> 5 0
t8~t9	350~300	-10
t 9~	300	0

F I G. 5




FIG. 6